



PRODUCT INFORMATION BULLETIN Z22K58



COMPRESSOR MOTOR

FALCON 10

INTRODUCING The SZ58-003-3 Compressor Drive Motor and Base Assembly. This motor is an FAA-PMA direct replacement for the Auxilec 1189. The SZ58-003-3 is a factory new motor manufactured under FAA-PMA and approved for installation on the Dassault Falcon 10. No modifications or other approvals are required to install this motor on the Falcon 10. Remove the failed 1189 and install the SZ58-003-3 Motor and Base Assembly using Kit Z22K58 which includes new hardware. TBO is 2,500 hours with a two year warranty.

ORDER THE Z22K58 KIT

kit includes:

1ea SZ58-003-3 Motor and Base Assembly

2ea MS25171-4S Boots

4ea MS21083N5 Lock Nuts

2ea MS3367-4-9 Cable ties

FACTORY NEW NET - \$6,000.00*

* Out-Right Sale Price \$10,500.00 - Return the old Auxilec 1189 Motor Core within 15 days and receive a \$4,500.00 credit.

The 1189 Core can be in ANY condition, repairable or not, but it must be complete including the base.

ZEE Systems, Inc.

AIRBORNE AIR CONDITIONING and HEATING

406 W. RHAPSODY - SAN ANTONIO, TEXAS 78216 U.S.A.

210-342-9761 - 800-988-COOL - FAX 210-341-2609

EMAIL info@zeeco-zeesys.com www.zeeco-zeesys.com